**Models:** **e-STUDIO 28**

**Subject:** **SERVICE DOCUMENTATION**

Because the design of the e-STUDIO28 is based on the e-STUDIO35/45, a new service manual will not be created. This bulletin describes the primary differences between the models.

In the tables below, the first number refers to the e-STUDIO45, the bracketed [ ] number refers to the e-STUDIO35, and the number in parens { } refers to the e-STUDIO28.

**SERVICE MANUAL**

| Paper supply | Cassette | Bypass feeding | | PFP | LCF |
|---|---|---|---|---|---|
| Paper size | | Size specified | Size not specified | | (A4/LT only) |
| A4,LT,B5 | 45[35]{28} | 45[35]{28} | 21[18]{18} | 45[35]{28} | 45[35]{28} |
| A4-R<br>B5-R<br>A5-R<br>LT-R<br>ST-R | 28[25]{25} | 28[25]{25} | 21[18]{18} | 28[25]{25} | |
| B4,LG | 24[21]{21} | 24[21]{21} | 21[18]{18} | 24[21]{21} | |
| A3,LD | 21[18]{18} | 21[18]{18} | 21[18]{18} | 21[18]{18} | |

(more)

Copyright-2001 Toshiba America Business Solutions, Inc. (TABS). This publication contains proprietary and confidential information retained for reference purpose by authorized TABS dealers. Unauthorized use of this information is prohibited. TABS makes no express or implied warranty, including implied warranties of merchantability for a particular purpose, with regard to this technical publication and disclaims any claim arising by reason of the possesion or use thereof.

**System Copy Speed**

| Copy Mode | | Copies/min |
|---|---|---|
| Single-sided originals<br>to<br>single-sided copies | 1 set<br>3 sets<br>5 sets | 36[30]{24}<br>39[31]{25}<br>41[33]{26} |
| Single-sided originals<br>to<br>two-sided copies | 1 set<br>3 sets<br>5 sets | 22[20]{19}<br>28[26]{23}<br>30[27]{24} |
| Two-sided originals<br>to<br>two-sided copies | 1set<br>3 sets<br>5 sets | 17[17]{17}<br>25[23]{22}<br>28[26]{23} |
| Two-sided originals<br>to<br>two-sided copies | 1set<br>3 sets<br>5 sets | 19[19]{18}<br>30[27]{23}<br>35[30]{25} |

**SERVICE HANDBOOK**

**1. Error code and self-diagnosis**

**1.2.3 Setting mode (08)**

**Code** 251: PM counter setting value (default value)

e-STUDIO45 : 150,000
e-STUDIO35 : 120,000
e-STUDIO28 : 93,000

**3. Preventive Maintenance (PM)**

| | e-STUD45 | e-STUD35 | e-STUD28 |
|---|---|---|---|
| 3.1 Maintenance | 150,000 | 120,000 | 93,000 |
| 3.2 Maintenance overhall | 450,000 | 360,000 | 270,000 |
| 3.3 Cleaning | 75,000 | 60,000 | 45,000 |

(more)

| PG-ITEM | e-STUDIO 28 Part # / Name | Note |
|---|---|---|
| 1-1 | 44216350000<br>F-COV-FRONT28 | |
| 1-16 | 44216363000<br>LBL-PM-45/35/28 | e-STUDIO45/35/28 |
| 7-19 | 44216460000<br>PWA-F-LGC-322 | |
| 7-20 | 44216421000<br>K-SRAM-T322MU | NAD |
| | 44216422000<br>K-SRAM-T322ME | ASD |
| 51-0 | 44216460000<br>PWA-F-LGC-322 | |

end